




OK-5119-H1

ASSEMBLY INSTRUCTION

1. INDOOR USE ONLY
2. REPLACE THE BULB AFTER THE BULB GETS COOL

Assembly steps:



- Step 1.** Tighten the screw(B) and pass the washers(C).(D) over the threaded tube(A2).
- Step 2.** Mount the glass shade(E) over washers(F) and mount the shell shade(G) onto threaded tube(A2) and secure with screw(H).
- Step 3.** Assembly canopy(I) to the threaded tube(H) and secure with the copper bead(J).
- Step 4.** Turn the bulb(K) to the tube(A1).
- Step 5.** Tighten the loop(L) on the top of threaded tube(A2).
- Step 6.** Tighten loop(L1) on the tube(N).
- Step 7.** Loosen screw(O) and pass canopy (P) over the tube(N).
- Step 8.** Tighten loop(Q) on the tube(N).
- Step 9.** Pass the main wire through the links of chain, loop(L1), canopy(P), tube(N) and loop(Q).
- Step 10.** Attach first link and last link(M) of chain to the loops(L1) and (L).
- Step 11.** Connect wire to the power supply cord.
- Step 12.** Raise the canopy(P) to ceiling and secure it by tightening the screw(O).
- Step 13.** Hang the Loop(Q) on the hook on ceiling.

After completed the above instruction, please check once more to ensure its safety. Then you may turn the power on.